

Inspection Photos

10/29/2018

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 456580

Inspection Doc. Number: 682504055

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 456580



Photo 1: Photo taken from the southwest corner of the location, facing north. Photo shows surface roughening has been used as a perimeter stormwater and erosion control BMP. Photo also shows topsoil pile on the south end of the location.



Photo 2: Photo taken from the southwest corner of the location, facing east. Photo shows surface roughening has been used as a perimeter stormwater and erosion control BMP. Photo also shows topsoil pile on the south end of the location.

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 456580



Photo 3: Photo taken from the south end of the location, facing north. Photo shows topsoil pile has been tracked.



Photo 4: Photo taken from the southeast end of the location, facing west. Photo shows operator has segregated the topsoil pile (left) and a "B" horizon (right).

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 456580



Photo 5: Photo taken from the northeast corner of the location, facing south. Photo shows surface roughening has been used as a perimeter stormwater and erosion control BMP. Photo also shows subsoil stockpile on the east end of the location.



Photo 6: Photo taken from the northeast corner of the location, facing west. Photo shows surface roughening has been used as a perimeter stormwater and erosion control BMP. Photo also shows topsoil pile on the south end of the location.