

Inspection Photos

10/29/2018

Operator: NIGHTHAWK PRODUCTION LLC -
10399

Location ID: 443310

Inspection Doc. Number: 682504059
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NIGHTHAWK PRODUCTION LLC - 10399
Location ID: 443310



Photo 1: Photo taken from the south end of the location, facing northwest. Photo shows vegetation over the location appears to be progressing to reclamation requirements.



Photo 2: Photo taken from the south end of the location, facing northeast. Photo shows vegetation over the location appears to be progressing to reclamation requirements.

Inspection Photos
Operator: NIGHTHAWK PRODUCTION LLC - 10399
Location ID: 443310



Photo 3: Photo taken from the north end of the location, facing west. Photo shows areas of the location that remain predominantly undesirable weedy plant species such as Russian thistle. Desirable perennial vegetation does appear to be establishing. Location appear to require additional time to meet uniform vegetative standards.



Photo 4: Photo taken from the north end of the location, facing east. Photo shows areas of the location that remain predominantly undesirable weedy plant species such as Russian thistle. Desirable perennial vegetation does appear to be establishing. Location appear to require additional time to meet uniform vegetative standards.

Inspection Photos
Operator: NIGHTHAWK PRODUCTION LLC - 10399
Location ID: 443310



Photo 5: Photo taken from the access road, south of the location, facing south. Photo shows access road remains evident and will likely require additional reclamation activities.



Photo 6: Photo taken from the access road, south of the location, facing south. Photo shows access road remains evident and will likely require additional reclamation activities.