

Inspection Photos

Location Name: Taylor 15-1 Location ID 327562 Inspection Date: 10/25/2018



Photo 1 – Tank Battery Sign



Photo 2 – Produced water pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Taylor 15-1 Location ID 327562 Inspection Date: 10/25/2018



Photo 3 – Weeds on tank battery



Photo 4 – Weeds on tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Taylor 15-1 Location ID 327562 Inspection Date: 10/25/2018



Photo 3 – Weeds at wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources