

Inspection Photos

Location Name: 05-103-08118 (NEWTON 2-1)

Location ID: 315237

Inspection: 679701571



location



Berm on west side of tank battery has inadequate height.