

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/22/2018

Submitted Date:

10/22/2018

Document Number:

689701961**FIELD INSPECTION FORM**

Loc ID 335848	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 21 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
------------------	------------------------------------	---	-------------------	--

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283784	WELL	PR	05/03/2007	GW	045-12002	N. PARACHUTE WF06B A36 596	PR
283788	WELL	PR	01/14/2007	GW	045-12004	N.PARACHUTE WF07B A36 596	PR
283789	WELL	PR	03/15/2006	GW	045-12005	N. PARACHUTE WF06D A36 596	PR
283791	WELL	PR	02/01/2011	GW	045-12006	N.PARACHUTE WF07D A36 596	PR
283796	WELL	PR	03/12/2007	GW	045-11997	N. PARACHUTE WF03D A36 596	PR
283798	WELL	SI	04/01/2017	GW	045-11996	N. PARACHUTE WF04D A36 596	SI
283800	WELL	PR	02/01/2014	GW	045-11995	N. PARACHUTE WF02B A36 596	PR
289595	WELL	PR	03/06/2007	GW	045-13804	N. PARACHUTE WF02D-DX A36 59	PR
294899	WELL	PR	03/10/2008	GW	045-15628	N. PARACHUTE WF15C-25 A36 59	PR
294900	WELL	PR	11/02/2008	GW	045-15629	N. PARACHUTE WF15A-25 A36 59	PR
294901	WELL	PR	10/13/2008	GW	045-15630	N. PARACHUTE WF07C-36 A36 59	PR
294902	WELL	PR	10/26/2008	GW	045-15631	N. PARACHUTE WF07A-36 A36 59	PR
294903	WELL	PR	10/13/2008	GW	045-15632	N. PARACHUTE WF06A-36 A36 59	PR

294909	WELL	PR	10/25/2008	GW	045-15633	N. PARACHUTE WF03C-36 A36 59	PR
294910	WELL	PR	10/25/2008	GW	045-15634	N. PARACHUTE WF02A-36 A36 59	PR
294912	WELL	PR	10/13/2008	GW	045-15636	N. PARACHUTE WF06C-36 A36 59	PR
294913	WELL	PR	10/23/2008	GW	045-15635	N. PARACHUTE WF02C-36 A36 69	PR

General Comment:

[Routine General Field Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	View of sign is obstructed by weeds/brush.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/26/2018
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	3-4" risers between WF 07D and WF 06D Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	24 hrs to lock out tag out. Corrective action date: 10/23/18 30 days to remove riser. Corrective action date: 11/22/18	Date:	10/25/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 17		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 80 bbls						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID: 283784	Type: WELL	API Number: 045-12002	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 283788	Type: WELL	API Number: 045-12004	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 283789	Type: WELL	API Number: 045-12005	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 283791	Type: WELL	API Number: 045-12006	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 283796	Type: WELL	API Number: 045-11997	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 283798	Type: WELL	API Number: 045-11996	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED				
Comment:				
Corrective Action:		Date:		
Facility ID: 283800	Type: WELL	API Number: 045-11995	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 289595	Type: WELL	API Number: 045-13804	Status: PR	Insp. Status: PR

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294899 Type: WELL API Number: 045-15628 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294900 Type: WELL API Number: 045-15629 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294901 Type: WELL API Number: 045-15630 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294902 Type: WELL API Number: 045-15631 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294903 Type: WELL API Number: 045-15632 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294909 Type: WELL API Number: 045-15633 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294910 Type: WELL API Number: 045-15634 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID: 294912 Type: WELL API Number: 045-15636 Status: PR Insp. Status: PR				

<u>Producing Well</u>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID:	294913	Type:	WELL
API Number:	045-15635	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass					
Berms	Pass					
Compaction	Pass					
		Gravel	Pass			
				Material Handling And Spill Prevention	Pass	
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401807786	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4619419
689701962	Inspection 689701961 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4619417