

Inspection Photos
Location Name:Zarlengo#14-4
Location ID: 320463



Photo#1 Production Tank and produced water pit



Photo#2 Separator and Gas Meter

Inspection Photos
Location Name:Zarlengo#14-4
Location ID: 320463



Photo#3 Wellhead



Photo#4 Corrective Action/Repair netting over produced water pit