

Inspection Photos
Location Name: Sparks Ridge Unit 2 H
API: 05-081-07450



Photo 1. Overview of location taken at entrance facing northeast. No wellhead sign.



Photo 2. No county road listed on battery sign located at entrance to location.

Inspection Photos
Location Name: Sparks Ridge Unit 2 H
API: 05-081-07450



Photo 3. Faded tank capacity.



Photo 4. Stained soil at wellhead.