

Inspection Photos

Operator: BP Production

API: 05-067-08817

Date: 10/24/2018



Photo 1. View of the project area from the eastern corner facing center.



Photo 2. View of the southeastern project area from the eastern corner facing southward. Revegetation is progressing with grasses and shrubs such as intermediate wheatgrass (*Thinopyron intermedium*), smooth brome (*Bromus inermis*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the northeastern project area from the eastern corner facing westward.



Photo 4. View of western project area from the southwestern corner facing northward.