

COLORADO C



99999999

TION COMMISSION
JRT☐ NOTICE OF UNSATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801

Denver, CO 80203

(303)894-2100

☒ NOTICE OF SATISFACTORY INSPECTIONAPI No. 05- *123 - 5408-1*LEASE NAME: *CEI - RLB #1*LOCATION: *NENW 12-7N-58W*OPERATOR: *Cowan*DATE: *4-3-97*INSPECTOR: *EBB*Insp. Type: *SR*Insp. Status: *PA*PA: ☒ Y

N

Pass/Fail: ☒ P

F

Viol.: Y

☒ N

NOV: Y

☒ N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))	<i>123 - 5408 PA = Y</i>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	<i>C</i>	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	<i>cultivated</i>	
Miscellaneous	<i>slight gravel noted in furrows</i>	<i>—</i>

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00204627

Site

To Jim McKee

Date 8/15/86 Time 3:50 PM

WHILE YOU WERE OUT

Name Paul Shelby

of Unidentified

Phone 595-3957

Telephoned	<input checked="" type="checkbox"/>	Please Call	<input checked="" type="checkbox"/>
Returned Your Call	<input type="checkbox"/>	Will Call Again	<input type="checkbox"/>
Wants To See You	<input type="checkbox"/>	RUSH	<input type="checkbox"/>

Message requested lease
clarification 120 AC.
not 160 AC.

Candi
OPERATOR