

**Inspection Photo
Mead 24-14
API # 045-06557
Inspection # 689302253**



Location Photo #1

Location Photo #2, unmarked/ unused flowline.

**Inspection Photo
Mead 24-14
API # 045-06557
Inspection # 689302253**



Location Photo #3, missing labels

Location Photo #4, missing labels

**Inspection Photo
Mead 24-14
API # 045-06557
Inspection # 689302253**



Location Photo #5, battery sign inaccurate.



Location Photo #6, improperly marked deadman

**Inspection Photo
Mead 24-14
API # 045-06557
Inspection # 689302253**



Location Photo #7, improperly marked deadman



Location Photo #8 , improperly marked deadman

**Inspection Photo
Mead 24-14
API # 045-06557
Inspection # 689302253**



**Location Photo #9 , improperly marked
deadman**