

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2018

Submitted Date:

11/01/2018

Document Number:

689702002**FIELD INSPECTION FORM**

Loc ID 336054	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>16700</u> Name of Operator: <u>CHEVRON USA INC</u> Address: <u>6301 DEAUVILLE BLVD</u> City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79706</u>				Findings: <u>27</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Haub, Mike	(970) 697-8385	MHaub@chevron.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276277	WELL	PR	02/16/2006	GW	045-10436	SKINNER RIDGE 598-25-2	PR
296980	WELL	PR	02/01/2011	GW	045-16242	SKR 598-25-CV-20	PR
296981	WELL	PR	10/10/2010	GW	045-16243	SKR 598-25-CV-13	PR
296982	WELL	PR	11/15/2010	GW	045-16244	SKR 598-25-CV-12	PR
296983	WELL	PR	10/21/2010	GW	045-16245	SKR 598-25-CV-10	PR
296984	WELL	PR	03/01/2018	GW	045-16246	SKR-598-25-CV 09	PR
296985	WELL	PR	11/10/2010	GW	045-16247	SKR 598-25-CV-17	PR
296986	WELL	PR	12/08/2010	GW	045-16248	SKR 598-25-CV-15	PR
296987	WELL	PR	11/10/2010	GW	045-16249	SKR 598-25-CV-16	PR
296988	WELL	PR	11/18/2010	GW	045-16250	SKR 598-25-CV-14	PR
296989	WELL	PR	01/11/2011	GW	045-16251	SKR 598-25-CV-22	PR
296990	WELL	PR	01/17/2011	GW	045-16252	SKR 598-25-CV-21	PR
296991	WELL	PR	11/10/2010	GW	045-16253	SKR 598-25-CV-18	PR
296992	WELL	PR	10/02/2010	GW	045-16254	SKR 598-25-CV-03	PR
296993	WELL	PR	12/20/2010	GW	045-16255	SKR 598-25-CV-01	PR
296994	WELL	PR	11/10/2010	GW	045-16256	SKR 598-25-CV-19	PR
296995	WELL	PR	09/15/2010	GW	045-16257	SKR 598-25-CV-02	PR
296996	WELL	PR	10/15/2010	GW	045-16258	SKR 598-25-CV-06	PR
296997	WELL	PR	10/09/2010	GW	045-16259	SKR 598-25-CV-11	PR

296998	WELL	PR	05/01/2018	GW	045-16260	SKINNER RIDGE 598-25-CV 08	PR
296999	WELL	PR	05/22/2012	GW	045-16261	SKR 598-25-CV-07	PR
297000	WELL	PR	10/08/2010	GW	045-16262	SKR 598-25-CV-05	PR
297001	WELL	PR	09/18/2010	GW	045-16263	SKR 598-25-CV-04	PR

General Comment:
[Routine FIU General Field Inspection](#)

Location**Lease Road:**

Type			
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank content not posted		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/04/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	877-257-6007	
Corrective Action:		Date: _____

Good Housekeeping:

Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 20		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	Not Posted	
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	276277	Type:	WELL	API Number:	045-10436	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	296980	Type:	WELL	API Number:	045-16242	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	296981	Type:	WELL	API Number:	045-16243	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	296982	Type:	WELL	API Number:	045-16244	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	296983	Type:	WELL	API Number:	045-16245	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	296984	Type:	WELL	API Number:	045-16246	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	296985	Type:	WELL	API Number:	045-16247	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	296986	Type:	WELL	API Number:	045-16248	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:					Date:				

Facility ID:	296987	Type:	WELL	API Number:	045-16249	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	296988	Type:	WELL	API Number:	045-16250	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	296989	Type:	WELL	API Number:	045-16251	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	296990	Type:	WELL	API Number:	045-16252	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	296991	Type:	WELL	API Number:	045-16253	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	296992	Type:	WELL	API Number:	045-16254	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	296993	Type:	WELL	API Number:	045-16255	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	296994	Type:	WELL	API Number:	045-16256	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing Well								
Corrective Action:						Date:			

Facility ID: 296995	Type: WELL	API Number: 045-16257	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:		Date:		
Facility ID: 296996	Type: WELL	API Number: 045-16258	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:		Date:		
Facility ID: 296997	Type: WELL	API Number: 045-16259	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:		Date:		
Facility ID: 296998	Type: WELL	API Number: 045-16260	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:		Date:		
Facility ID: 296999	Type: WELL	API Number: 045-16261	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:		Date:		
Facility ID: 297000	Type: WELL	API Number: 045-16262	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:		Date:		
Facility ID: 297001	Type: WELL	API Number: 045-16263	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
		Culverts	Pass			
Gravel	Pass					
Ditches	Pass					
		Gravel	Pass			
Culverts	Pass					
		Compaction	Pass			
Check Dams	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	290171	1433616	
	290171	1433616	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702003	Inspection # 689702001 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4630498