

## Inspection Photos

**Location Name:** Capehart-66N64W /29NWNE

**Location #:** 330382



Colorado Oil & Gas Conservation Commission  
40.46247, -104.57103, 1414.0m, 212°  
2018/11/01 04:50:52 PM

**Photo #1**

**Capehart 31-29 (API # 05-123-18999) wellsite**

**TA: Temporarily Abandoned**



Colorado Oil & Gas Conservation Commission  
40.45854, -104.57263, 1407.0m, 211°  
2018/11/01 04:23:26 PM

**Photo #2**

**Capehart 1, 31-29, 42-29 Battery**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Capehart-66N64W /29NWNE

**Location #:** 330382



**Photo #3**

**Capehart 31-29 wellsite**

**Weeds | Unused Equipment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources