

Inspection Photos
Location Name: Baughman Farms
API: 009-05182



Photo 1. Site looking from East to West. Dark area is low area that should be recontoured.



Photo 2. Plastic pipe.