

Inspection Photos

Loc#436676

Operator: Sandridge

Inspection Number: 692400264

Inspection Date: 10/30/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northwest.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility



Photo#2:

Top Soil has been Salvaged and stockpiled at West side of Location.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility



Photo#3:
Silt fence needs repair on North & West sides of Location.



Photo#4:

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility