

Inspection Photos

Loc#445005

Operator: Sandridge

Inspection Number: 692400267

Inspection Date: 10/31/2018





Photo#1:
Topsoil has been segregated and protected.

October 31 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#445005 Surprise Unit



Photo#2:
Topsoil has been segregated and protected.

October 31 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#445005 Surprise Unit



Photo#3:
Bmp repairs & installations were in progress.

October 31 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#445005 Surprise Unit