

## Inspection Photos

Location Name: 05-103-09777 (PARK MOUNTAIN FEDERAL 9006)

Location ID: 316094

Inspection: 679701622



Location looking west



Tank battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: 05-103-09777 (PARK MOUNTAIN FEDERAL 9006)

Location ID: 316094

Inspection: 679701622



Gas meter building and separator



Nearest public road missing "CR 23"



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources