

Inspection Photos

Operator: BP Production

API: 05-067-07264

Date: 10/24/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), sand dropseed (*Sporobolus airoides*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the Russian knapweeds (*Acroptilon repens*) west of the project area.



Photo 5. View of musk thistles (*Cirsium arvense*) west of the project area.