

# Construction and Stormwater Inspection

November 6, 2018

Operator: PETRO OPERATING COMPANY LLC- #10583

Location ID: 458074

Inspection Document #: 682404151

Adams County, CO

NESE Section 2 T1S R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BEF PAD /1S66W2  
Location ID: 458074



**Photo 1.** Photo taken from a two-track off the frontage road, facing West. Photo illustrates adjacent areas being contoured for residential housing development. Operator is coordinating with the developer on the construction of the location. Silt fence BMP was observed throughout the entire disturbance perimeter.

Inspection Photos  
Location Name: BEF PAD /1S66W2  
Location ID: 458074



**Photo 2.** Photo taken from a two-track off the frontage road, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: BEF PAD /1S66W2  
Location ID: 458074



**Photo 3.** Photo taken from a two-track off the frontage road, facing Northwest.  
See comments under Photo 1.