

Final Reclamation Inspection

November 6, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-15038

Inspection Document #: 682404161

Weld County, CO

SESE Section 17 T3N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UPRC #17-16J
API: 05-123-15038



Photo 1. Photo taken from the southern location, facing East. Well has been plugged and abandoned. Photo illustrates final reclamation activities (i.e., straw crimped mulch and seeded). Operator shall continue to control weeds and erosion until the Location meets Rule 1004 standards.

Inspection Photos
Location Name: UPRC #17-16J
API: 05-123-15038



Photo 2. Photo taken from the southern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: UPRC #17-16J
API: 05-123-15038



Photo 3. Photo taken north location, facing North. Appears the Operator has performed final reclamation activities along flowline removal areas.