

Inspection Photos

Operator: BP Production

API: 05-067-09641

Date: 10/30/2018



Photo 1. View of the project area from the northeastern corner facing center. Graveled well pad is not reclaimed.



Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of the northern project area from the northeastern corner facing westward. Well pad on left is approximately 5-8 feet above ground surface on right.



Photo 4. View of piled gravel and kochia on well pad. Some well pad fill material is removed.



Photo 5. View of the western project area from the southwestern corner facing northward.