

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. Battery sign with inaccurate well information at entrance.

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 3. Soil staining and open rat hole.



Photo 4. Soil staining.

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 5. 2 Conductors, 1 sign.



Photo 6. Frac sand.