

## Inspection Photos

Location Name: Graefe #1 well and tank battery Location ID 317527, Remediation #10043

Inspection Date: 11/2/2018



Photo 1 – Tank Battery Sign



Photo 2 – Former Steel AST product and produced water tank battery, from west end looking east.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Graefe #1 well and tank battery Location ID 317527, Remediation #10043

Inspection Date: 11/2/2018



**Photo 3 – Produced water injection line, near former injection building and adjacent former tank battery.**



**Photo 4 – Debris and unused tanks stored on location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Graefe #1 well and tank battery Location ID 317527, Remediation #10043

Inspection Date: 11/2/2018



Photo 5 –Graefe #1, from northwest corner of excavation, looking east, southeast.



Photo 6 – Graefe #1, from northwest corner of excavation, looking south.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources