

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2018

Submitted Date:

11/08/2018

Document Number:

693700071**FIELD INSPECTION FORM**

Loc ID 317527 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 36200Name of Operator: GRYNBERG\* JACK DBA GRYNBERG PETROLEUM COAddress: 3600 S. YOSEMITE ST - STE 900City: DENVER State: CO Zip: 80237-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Evins, Bret		bret.evins@state.co.us	
Scott Schultz		scott.schultz@coag.gov	
Randy Edelen		r.edelen@grynberg.com	
Enforcement, COGCC		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239188	WELL	SI	03/01/2017	OW	123-06129	GRAEFE 1	EI

**General Comment:**

Followup to Remediation #10043. Tank Battery has been dismantled and conditions have not changed since documentation by Inspection #691200398



**Environmental****Spill/Remediation:**

Comment: Excavation has occurred around Graefe #1 wellhead around tank battery injection house and around tank battery. Tank battery has been dismantled and excavations remain open. Confirmation soil samples from excavations have not been received.

Corrective Action: Operator shall submit Form 27 Supplemental Report with excavation confirmation soil samples in reference to Remediation Project #10043. Form 27 Supplemental original due date was April 10, 2017. Operator shall backfill excavations after review of confirmation soil sample results by COGCC.

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700072	Graefe 1 Site Photos 11-2-2018	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640070">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640070</a>