

# *Inspection Photos*

*Loc#417618*

*Operator: Berry*

*Inspection Number: 692400308*

*Inspection Date: 10/19/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to North.

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Berry Loc#417618



## Photo#2

Interim Reclamation area that is progressing though cattle have broken through fence are grazing area heavily.

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Berry Loc#417618





Photo#3:

View of Location to South; insert of Anchor that needs Marked or removed .

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Berry Loc#417618