

**Inspection Photos**  
**Location Name:** Roth-66N64W /30NENW  
**Location #:** 332319



**Photo #1**

**Roth 21-30** (API # 05-123-22144) wellsite

**Temporarily Abandoned – TA'd**

**Unused Equipment – Methanol pump / tank**



**Photo #2**

**Roth 5, 21-30 Battery**

**Shut-In**

