

Lantz SG 44-23
Api # 05-045-21686
Inspection # 689702053



Lantz SG 44-23
Api # 05-045-21686
Inspection # 689702053



Location photo. Weeds on location.

Lantz SG 44-23
Api # 05-045-21686
Inspection # 689702053



Weeds on location.

Lantz SG 44-23
Api # 05-045-21686
Inspection # 689702053



Weeds on location.

Lantz SG 44-23
Api # 05-045-21686
Inspection # 689702053



Stained material at separators.

Lantz SG 44-23
Api # 05-045-21686
Inspection # 689702053



No capacity on tank label.

Lantz SG 44-23
Api # 05-045-21686
Inspection # 689702053



No capacity on tank label.