

Inspection Photos

11/8/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312233

Inspection Doc. Number: 682504103

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from well location, facing north. Previous inspection required barrels to be placed into secondary containment. Photo shows barrels have not been placed into secondary containment.



Photo 2: Photo taken from meter shed, facing south. Previous inspection required barrels to be placed into secondary containment. Photo shows barrels have not been placed into secondary containment.



Photo 3: Photo taken from meter shed, facing south. Previous inspection required plastic tank to be placed back. Operator appears to have installed secondary containment and returned the tank. Previous inspection also required operator to replace signage/placards on tank. Photo shows signage/placards have not been replaced.



Photo 4: Continued from photo 3. Photo shows signage/placards have not been replaced.