

# Inspection Photos

11/8/2018

Operator: WESTERN OPERATING COMPANY -  
95620

Location ID: 312292

Inspection Doc. Number: 682504105

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the access road. Photo shows erosion degradation occurring at the cattle guard has not been repaired.



**Photo 2:** Photo taken from the access road. Photo shows erosion degradation occurring at the cattle guard has not been repaired. Photo also shows ~ 2 feet of soil has been washed out beneath the cattle guard.



**Photo 3:** Photo taken from the access road. Photo shows erosion degradation occurring at the cattle guard has not been repaired.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312292



**Photo 4:** Photo taken from the west end of the well pad. Photo shows areas of the location where additional reclamation activities appear to have been conducted.



**Photo 5:** Photo taken from the west end of the pad (east end of pit). Photo shows gully erosion from the pit has not been addressed.



**Photo 6:** Photo taken from the south end of the pad, facing south. Photo shows additional reclamation activities appear to have been conducted on the spill areas to the south of the pit.



**Photo 7:** Photo taken from the south end of the pad, facing west. See comments under photo 6.



**Photo 8:** Photo taken from the south end of the pit, facing south. See comments under photo 6.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312292



**Photo 9:** Photo taken from the southwest end of the pit, facing east. See comments under photo 6.



**Photo 10:** Photo taken from the southwest end of the pit, facing northwest. See comments under photo 6.



**Photo 11:** Photo taken from the west end of the pit, facing west. See comments under photo 6.



**Photo 12:** Photo taken from the north end of the location. Photo shows trailer containing straw erosion logs.