

Inspection Photos

Loc#335016

Operator: Caerus Washco

Inspection Number: 692400273

Inspection Date: 10/18/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from top of Cut slope to Northeast.

October 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Washco PuckettLoc#335016



Photo#2:
View to Southeast along un-reclaimed fill slope.

October 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Washco PuckettLoc#335016



Photo#3:

Overview of Location to West; Insert is close up of Pad area that has been mulched / seeded (?).

October 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Washco PuckettLoc#335016