

Inspection Photo
Hilltop 2F2 Ranch RWF 14-33
API # 045-13828
Inspection # 689302339



Location Photo #1



Location Photo #2

Inspection Photo
Hilltop 2F2 Ranch RWF 14-33
API # 045-13828
Inspection # 689302339



Location Photo #3



Location Photo #4, uncontrolled weeds near wellheads.



**Inspection Photo
Hilltop 2F2 Ranch RWF 14-33
API # 045-13828
Inspection # 689302339**



Location Photo #5, uncontrolled weeds near Tank battery.



Location Photo #6, Uncontrolled weeds behind separators.



Inspection Photo
Hilltop 2F2 Ranch RWF 14-33
API # 045-13828
Inspection # 689302339



Location Photo #7, unused equipment removed.