


Inspection Photos

Location Name: 05-103-10498 (BIG JIMMY UNIT DOUBLE WILLOW UNIT 8610C A07 497)

Location ID: 316426

Inspection: 679701673



Location looking west



Well head



Inspection Photos

Location Name: 05-103-10498 (BIG JIMMY UNIT DOUBLE WILLOW UNIT 8610C A07 497)

Location ID: 316426

Inspection: 679701673 Fluid spraying out



Location looking south



Fluid is sprayed out every 3 seconds from pump next to separator into air 2' to 4'.

Inspection Photos

Location Name: 05-103-10498 (BIG JIMMY UNIT DOUBLE WILLOW UNIT 8610C A07 497)

Location ID: 316426

Inspection: 679701673

Fluid spraying out



separator



Fluid on ground next to separator

Inspection Photos

Location Name: 05-103-10498 (BIG JIMMY UNIT DOUBLE WILLOW UNIT 8610C A07 497)

Location ID: 316426

Inspection: 679701673



Fluid on ground next to separator



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources