

Inspection Photos

Location Name: 05-103-10782 (FEDERAL 4S-95-1-21DP)

05-103-10782 (FEDERAL 4S-95-1-31D)

Location ID: 285160

Inspection: 679701680



Location looking southeast



Well head looking southeast



Inspection Photos

Location Name: 05-103-10782 (FEDERAL 4S-95-1-21DP)

05-103-10782 (FEDERAL 4S-95-1-31D)

Location ID: 285160

Inspection: 679701680



Pig station



Separators



Inspection Photos

Location Name: 05-103-10782 (FEDERAL 4S-95-1-21DP)

05-103-10782 (FEDERAL 4S-95-1-31D)

Location ID: 285160

Inspection: 679701680



Produced water battery



separators

Inspection Photos

Location Name: 05-103-10782 (FEDERAL 4S-95-1-21DP)

05-103-10782 (FEDERAL 4S-95-1-31D)

Location ID: 285160

Inspection: 679701680



50 bbl tank without labeling



6 bbl tank without labeling



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 05-103-10782 (FEDERAL 4S-95-1-21DP)

05-103-10782 (FEDERAL 4S-95-1-31D)

Location ID: 285160

Inspection: 679701680



Gas meters



Condensate battery

Inspection Photos

Location Name: 05-103-10782 (FEDERAL 4S-95-1-21DP)

05-103-10782 (FEDERAL 4S-95-1-31D)

Location ID: 285160

Inspection: 679701680



Unused separator



Disconnected separator

