

## Inspection Photos

Location Name: 05-103-07986 (FOUNDATION CREEK B 7403)

Location ID: 315144

Inspection: 679701682



Location looking northwest



Tank battery



## Inspection Photos

Location Name: 05-103-07986 (FOUNDATION CREEK B 7403)

Location ID: 315144

Inspection: 679701682



**Tank battery secondary containment wall bent**

