


**Inspection Photos**  
**Location Name: MOORE 3-11 MH**  
**Location ID: 05-103-09032**  
**Inspection: 679701689**



**Photo 1. Location looking southwest.**



**Photo 2. Missing NFPA label.**

## Inspection Photos

Location Name: MOORE 3-11 MH

Location ID: 05-103-09032

Inspection: 679701689



**Photo 3. Debris on location next to wellhead.**



**Photo 4. Barrel without label or containment next to wellhead.**



## Inspection Photos

Location Name: MOORE 3-11 MH

Location ID: 05-103-09032

Inspection: 679701689



**Photo 5. Pit in inside tank berm.**

