

Inspection Photos

Loc#335985

Operator: Caerus

Inspection Number: 692400309

Inspection Date: 10/18/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View of Location from entry to Northwest.

October 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335985



Photo#2:
View of Location from entry to Northeast.

October 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335985



Photo#3:

View of Location from Northwest to entry at Southeast.

October 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335985



Photo#4:

Reclamation activities have been conducted on Fill Slopes along West side of site.

October 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335985