

Inspection Photos

API#077-09060

Operator: Caerus

Inspection Number: 692400235

Inspection Date: 10/16/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mann Federal API#077-09060



Photo#2:
Close up view of vegetation & ground conditions.

October 16, 2018



Photo#3:
Area approximately 20 ft. x 40 ft. in center of location infested with Cheat grass.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mann Federal API#077-09060



Photo#4:
View of Reference area vegetation to West of site.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mann Federal API#077-09060



Photo#5:
View of Access Road remaining.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mann Federal API#077-09060