

Final Reclamation Inspection

November 9, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-10238

Inspection Document #: 682404183

Weld County, CO

NESE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HAROLD R. MIXON GAS UNIT #2
API: 05-123-10238



Photo 1. Photo taken west of the location, facing East. Photo illustrates a land use change to mining development. No visual evidence of oil and gas equipment at the well location; battery location is still being used on an active well by another Operator.