

# Final Reclamation Inspection

November 9, 2018

Operator: TOP OPERATING COMPANY - 39560

API: 05-123-09062

Inspection Document #: 682404193

Weld County, CO

SENE Section 25 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: FLORENCE B. SCHNEIDER #4

API: 05-123-09062



**Photo 1.** Photo taken south of the well location, facing North. Photo illustrates a land use change to mining development. No visual evidence of oil and gas equipment at the Location.