

## Inspection Photos

Location Name: SHENANDOAH 6-18

Location ID: 05-103-08718

Inspection: 679701699



Photo 1. Location looking south



Photo 2. Location looking northwest



## Inspection Photos

Location Name: SHENANDOAH 6-18

Location ID: 05-103-08718

Inspection: 679701699



**Photo 3. Weeds in pit**

