

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2018

Submitted Date:

11/05/2018

Document Number:

689702017

FIELD INSPECTION FORM

Loc ID 435806 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 22 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:


Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435798	WELL	PR	03/20/2014	GW	045-22297	NOLTE 44B-14	PR
435799	WELL	PR	07/09/2014	GW	045-22298	NOLTE 13B-13	PR
435800	WELL	PR	03/11/2014	GW	045-22299	NOLTE 11B-24	PR
435801	WELL	PR	04/08/2014	GW	045-22300	NOLTE 14C-13	PR
435802	WELL	PR	07/18/2014	GW	045-22301	NOLTE 44A-14	PR
435803	WELL	PR	06/29/2014	GW	045-22302	NOLTE 43C-14	PR
435804	WELL	PR	03/23/2014	GW	045-22303	NOLTE 11A-24	PR
435805	WELL	PR	09/17/2014	GW	045-22304	NOLTE 14D-13	PR
435807	WELL	PR	07/21/2014	GW	045-22305	NOLTE 13D-13	PR
435808	WELL	PR	03/15/2014	GW	045-22306	NOLTE 44C-14	PR
435809	WELL	PR	05/08/2014	GW	045-22307	NOLTE 13C-13	PR
435810	WELL	PR	07/05/2014	GW	045-22308	NOLTE 13A-13	PR
435811	WELL	PR	07/12/2014	GW	045-22309	NOLTE 43B-14	PR
435812	WELL	PR	04/24/2014	GW	045-22310	NOLTE 14A-13	PR
435813	WELL	PR	04/12/2014	GW	045-22311	NOLTE 14B-13	PR
435814	WELL	PR	07/11/2014	GW	045-22312	NOLTE 43A-14	PR
435989	WELL	PR	03/04/2014	GW	045-22325	NOLTE 11C-24	PR

General Comment:

Routine FIU General Field Inspection



Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	3 tanks in battery has labels in disrepair. Tank at pump house no label posted.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 01/06/2019
Emergency Contact Number:			
Comment:	866-580-9382		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around perimeter berms and in storm water bmps.		
Corrective Action:	Comply with Rule 603.f .		Date: 11/16/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	435798	Type:	WELL	API Number:	045-22297	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	435799	Type:	WELL	API Number:	045-22298	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	435800	Type:	WELL	API Number:	045-22299	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	435801	Type:	WELL	API Number:	045-22300	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	435802	Type:	WELL	API Number:	045-22301	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	435803	Type:	WELL	API Number:	045-22302	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	435804	Type:	WELL	API Number:	045-22303	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	435805	Type:	WELL	API Number:	045-22304	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 435807	Type: WELL	API Number: 045-22305	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435808	Type: WELL	API Number: 045-22306	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435809	Type: WELL	API Number: 045-22307	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435810	Type: WELL	API Number: 045-22308	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435811	Type: WELL	API Number: 045-22309	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435812	Type: WELL	API Number: 045-22310	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435813	Type: WELL	API Number: 045-22311	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435814	Type: WELL	API Number: 045-22312	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: 435989 Type: WELL API Number: 045-22325 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Culverts	Pass			
Compaction	Pass					
				Material Handling And Spill Prevention		
Berms	Pass					
		Gravel	Pass			
Check Dams	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401831445	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4638654
689702018	Inspection 689702017 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4638644