

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Nov 7, 2018 9:15:03 AM MST
Server Receive Date:	Nov 7, 2018 9:15:37 AM MST
Reference Number:	20181107-1891251543
Location:	557 Airpark Dr, Durango, CO 81303, USA Nov 7, 2018 9:14:53 AM MST [View Map]

Information

Name	reclamationtablet
Date	Nov 6, 2018
Well Name	KNIGHT GAS UNIT B 1
Location Name (Other)	knight 1
API Number	50670784200
Location API (Other)	050670507600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Seeding Other Install Wattles


Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

installed erosion logs and seeded/mulched the slopes above and below the pad

Notes

we also seeded/mulched the culvert area. mulch was a steep slope mulch.