

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2018

Submitted Date:

11/08/2018

Document Number:

693700071**FIELD INSPECTION FORM**
 Loc ID 317527 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 36200Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM COAddress: 3600 S. YOSEMITE ST - STE 900City: DENVER State: CO Zip: 80237-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Evins, Bret		bret.evins@state.co.us	
Enforcement, COGCC		dnr_cogccenforcement@state.co.us	
Randy Edelen		r.edelen@grynberg.com	
Scott Schultz		scott.schultz@coag.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239188	WELL	SI	03/01/2017	OW	123-06129	GRAEFE 1	EI

General Comment:

Followup to Remediation #10043. Tank Battery has been dismantled and conditions have not changed since documentation by Inspection #691200398

Environmental**Spill/Remediation:**

Comment: Excavation has occurred around Graefe #1 wellhead around tank battery injection house and around tank battery. Tank battery has been dismantled and excavations remain open. Confirmation soil samples from excavations have not been received.

Corrective Action: Operator shall submit Form 27 Supplemental Report with excavation confirmation soil samples in reference to Remediation Project #10043. Form 27 Supplemental original due date was April 10, 2017. Operator shall backfill excavations after review of confirmation soil sample results by COGCC.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401833094	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640074
693700072	Graefe 1 Site Photos 11-2-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640070