

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2018

Submitted Date:

11/08/2018

Document Number:

689702051**FIELD INSPECTION FORM**Loc ID 423081 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name      | Phone | Email                                     | Comment                   |
|-------------------|-------|---|---------------------------|
| Pesicka, Conor    |       | conor.pesicka@state.co.us                 |                           |
| Kellerby, Shaun   |       | shaun.kellerby@state.co.us                |                           |
| , Caerus Piceance |       | COGCC.inspections@caerus<br>oilandgas.com | Piceance inspections only |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 423048      | WELL | PR     | 06/07/2012  | GW         | 045-20639 | Federal 25-4C (PE-25) | PR          |
| 423067      | WELL | PR     | 05/18/2012  | GW         | 045-20652 | Federal 25-5B (PE-25) | PR          |
| 423069      | WELL | PR     | 06/07/2012  | GW         | 045-20654 | Federal 25-4A (PE-25) | PR          |
| 423076      | WELL | PR     | 05/13/2012  | GW         | 045-20661 | Federal 25-4B (PE-25) | PR          |
| 423094      | WELL | PR     | 06/07/2012  | GW         | 045-20670 | Federal 25-5C (PE-25) | PR          |
| 423096      | WELL | SI     | 10/01/2017  | GW         | 045-20671 | Federal 25-5A (PE-25) | SI          |
| 423100      | WELL | PR     | 05/10/2012  | GW         | 045-20673 | Federal 25-4D (PE-25) | PR          |
| 423105      | WELL | PR     | 06/07/2012  | GW         | 045-20677 | Federal 25-5D (PE-25) | PR          |

**General Comment:**

Routine FIU General Field Inspection

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | CONTAINERS   |       |            |
| Comment:             | Labels on containers at wells are faded and peeling.   |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.b.  | Date: | 01/09/2019 |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | BATTERY  |       |            |
| Comment:             | The phone number for local emergency services (911 where available) and the public road used to access the site is not posted on battery sign. |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.b.  | Date: | 01/09/2019 |

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                          |       |            |
|--------------------|--------------------------|-------|------------|
| Type               | WEEDS                    |       |            |
| Comment:           | Weeds on location.       |       |            |
| Corrective Action: | Comply with Rule 603.f . | Date: | 11/20/2018 |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 423048         | Type: | WELL | API Number: | 045-20639 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 423067         | Type: | WELL | API Number: | 045-20652 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 423069         | Type: | WELL | API Number: | 045-20654 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 423076         | Type: | WELL | API Number: | 045-20661 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 423094         | Type: | WELL | API Number: | 045-20670 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 423096         | Type: | WELL | API Number: | 045-20671 | Status: | SI | Insp. Status: | SI |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 423100         | Type: | WELL | API Number: | 045-20673 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 423105         | Type: | WELL | API Number: | 045-20677 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           | Pass            |                         |                       |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
|                  |                 | Ditches                 | Pass                  |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |
| Ditches          | Pass            |                         |                       |  |                          |         |
|                  |                 | Gravel                  | Pass                  |  |                          |         |
| Compaction       | Pass            |                         |                       |  |                          |         |
|                  |                 | Culverts                | Pass                  |  |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 401833743    | INSPECTION SUBMITTED           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640648">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640648</a> |
| 689702052    | Inspection 689702051 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640642">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640642</a> |