

Inspection Photos
Location Name: PARKER 1
Location ID: 336465



Colorado Oil & Gas Conservation Commission
40.12209, -104.81735, 1453.0m, 43°
2018/11/16 13:31:59



Colorado Oil & Gas Conservation Commission
40.1215, -104.81713, 1496.0m, 304°
2018/11/16 13:35:00

PHOTO 1: WELLHEAD

PHOTO 2: TANK BATTERY

Inspection Photos
Location Name: PARKER 1
Location ID: 336465



PHOTO 3: STAINED SOIL UNDER PRIME MOVER

PHOTO 4: UNMARKED UNUSED RISER

Inspection Photos
Location Name: PARKER 1
Location ID: 336465



PHOTO 5: UNUSED EQUIPMENT

PHOTO 6: TRASH INSIDE WELLHEAD FENCE

Inspection Photos
Location Name: PARKER 1
Location ID: 336465



Colorado Oil & Gas Conservation Commission
40.12211, -104.81745, 1462.0m, 341°
2018/11/16 13:33:23

PHOTO 7: VALVES LEAKING