

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2018

Submitted Date:

11/16/2018

Document Number:

692600809**FIELD INSPECTION FORM**
 Loc ID 304579 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266581	WELL	PR	05/31/2007	GW	125-08723	GODSEY 31-20	PR

**General Comment:**Routine Inspection

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Trail through farm ground			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Lease sign by unit			
Corrective Action:				Date:
Type	OTHER			
Comment:	Lease sign by meter run			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Metal panels around unit and wellhead			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Wire panels around meter run			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Pump Jack	# 1			corrective date
Comment:	Jensen unit			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric motor			
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Electric panel and telemetry equipment at meter run (bellows meter for domestic use at meter run)			
Corrective Action:				Date:

Type: Gas Meter Run	# 1		
Comment:	Meter run in metal box 620' NNW of wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Gas separator in metal box 620' NNW of wellhead		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	266581	Type:	WELL	API Number:	125-08723	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Meter run is 620' NNW of wellhead on south side of CR 33								
Corrective Action:							Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT