

**Inspection Photos**  
**Location Name: Ignacio 33-8 #2 Pit**  
**Pit Facility ID #105402**



**10/18/18 – Augering three sample locations.**



**Horizon Environmental Services attempting to extend borings to 6'.**

**Inspection Photos**  
**Location Name: Ignacio 33-8 #2 Pit**  
**Pit Facility ID #105402**



**One of three sample locations.**



**Location of sample points in relation to Ignacio 33-8 #2 meter shack.**

**Inspection Photos**  
**Location Name: Ignacio 33-8 #2 Pit**  
**Pit Facility ID #105402**



**10/19/18 – Extending sample locations to 6’.**



**Samples collected from a depth of 6’.**