

Inspection Photos

11/19/2018

Operator: MALLARD EXPLORATION LLC - 10670

Location ID: 454592

Inspection Doc. Number: 682504180

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 1: Photo taken from the north end of the location, facing west. Photos 1-3 provide an overview of the location from west, south, to east



Photo 2: See comments under photo 1.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 3: See comments under photo 1.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 4: Photo taken from the sediment trap on the north end of the location. Photo shows outlet appears to be in proper functioning condition.



Photo 5: Photo taken from the north end of the location, facing east. Photo shows sediment trap and stormwater ditch.



Photo 6: Photo taken from the north end of the location, facing west. Photo shows sediment trap and stormwater ditch.



Photo 7: Photo taken from the northwest corner of the pad, facing south. Photo shows topsoil stockpile and straw wattle stormwater BMP along the base.



Photo 8: Photo taken from the northwest corner of the pad, facing southwest. Photo shows topsoil stockpile and straw wattle stormwater BMP along the base



Photo 9: Photo taken from the northwest corner of the pad, facing southeast. Photo shows topsoil stockpile and straw wattle stormwater BMP along the base



Photo 10: Photo taken from the northwest corner of the pad, facing southwest. Photo shows vehicle traffic appears to have traveled over the surface roughening.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 11: Photo of the two producing wells on the pad.



Photo 12: Photo taken from the location, facing west. Photos 12-19 shows equipment/facilities on location.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 13:





Photo 14:

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 15: Produced water tank. 210 bbl



Photo 16: Produced water tank.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 17:



Photo 18:

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 19:



Photo 20: Photo taken from the south end of the location, facing southeast. Photo shows vehicle traffic has been traveling off the pad and over stormwater ditch in order to exit the location. This is not compliant with 1002.e



Photo 21: Photo taken from the access road on the south end of the location, facing west. Photo shows vehicle traffic has been traveling off the pad and over stormwater ditch in order to exit the location. This is not compliant with 1002.e