

## Inspection Photos

Location Name: BANTA RIDGE FED 16-18-1S-103

Location ID: 05-103-10410

Inspection: 679701857



**Photo 1. Location looking north.**



**Photo 2. Tank without labels.**



## Inspection Photos


Location Name: BANTA RIDGE FED 16-18-1S-103

Location ID: 05-103-10410

Inspection: 679701857



**Photo 3. Wellhead valve leaking gas at handle.**



**Photo 4. Fluid dripping from wellhead pan unto ground.**