

Inspection Photos

Location Name: BANTA RIDGE FED 13-17-1S-103

Location ID: 05-103-10421

Inspection: 679701859



Photo 1. Location looking north.



Photo 2. Tank without labels.



Inspection Photos

Location Name: BANTA RIDGE FED 13-17-1S-103

Location ID: 05-103-10421

Inspection: 679701859



Photo 3. Container without label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources