

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2018

Submitted Date:

11/20/2018

Document Number:

690300385**FIELD INSPECTION FORM**

Loc ID 316351 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORTH WORTH State: TX Zip: 76102**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Arauza, Steven		steven.arauza@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

General Comment:

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 60

Comment: Inspection to assess impact of Spill#459033. Sunny, 40F, no wind. ~14 bbl into lined SPCC for tank battery. ~45 bbl onto surface east of battery. ~50 bbl recovered w vac truck. Soil has been excavated to ~1 ft bgs in area east of tank battery. Soils are stockpiled on bermed HDPE liner.

Corrective Action: PER F-19 COA: Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in another Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation such as landfarming contaminated soil is required. Landfarming must also be approved by surface owner. Documentation must include a figure showing spill area with sample locations plus laboratory results.

Date: 12/20/2018

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401846636	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4651322
690300386	Insp photos 11-13-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4651321